MARYLAND GEOLOGICAL SURVEY Merryman Hall The Johns Hopkins University Baltimore, Maryland 21218 (301) 235-0771

COUNTIES (MD/PA) _	WASHINGTON/FRANKLIN
M&D milestone no.	97 (100)
MHT-HSI no.	WA-I-484

PROTECTED ENDANGERED MISSING

FIELD SHEET: MASON & DIXON LINE, MARYLAND-PENNSYLVANIA BOUNDARY MARKER SURVEY

LOCATION: USGS 7.5'quadrangle Smithsburg 1953, 1971 18.27573.439979 bench mark/date BM 645 (1939) original site/Moved/date 1767 Off N/S Millers Church Road, Rocky Forge, MD. About 2 miles N of Leitersburg, MD; about 2½ miles SW of Waynesboro, PA; W of Antietam Creek; at point about 500' N of Millers Church Rd, about 1200' E of Shoemaker Rd; near top of hill in back of Belew house, against N/S wire fence separating rolling open field (to N) & Belew (over) DIRECTIONS TO SITE:

From M&D 96 (99): continue W on Lyons Rd about 0.5 mile to its end at PA 316/MD 60; turn left (S) & follow about 0.55 mile to junction of Millers Church Rd; turn right (W) & follow about 0.6 mile to Belew house (N/S). Park & ask permission (over) DESCRIPTION/MEASUREMENTS: original/replica/replacement/date 1767; squared oolitic

limestone post; standing about 1' above ground; P on N/S, M on S/S
N face (PA): 11½" wide x 13½" high; P & most of circle panel distinct; no fluting
or margins remain; surfaces very weathered & nicked

E face:

wide x 13" high; most of face above ground gone (huge chunk); part of face remaining very weatherworn ll%" wide x 13" high; M indistinct; no fluting or margins remain; surfaces very weathered & nicked; chips all edges & corners S face (MD): W face:

114" wide x 131/2" high; no fluting or margins remain; surfaces very weatherworn; chips all edges & corners
still cracking from setting of BM disk in apex; huge chunk out of
top E edge; big chips all edges & corners; weatherworn, no planes
BM 645 (1959) USCEGS triangulation station disk in apex top:

bench mark:

CONDITION OF MARKER/FOUNDATION: EXEKTIONIZED AND FAIR / Deterior of deterior o 1900-03 Resurvey notes (order no.100), as in MGS Vol. 7, 1908, p. 89 100. Milestone No. 97, M. & D., 1767. West of Little Antietam Creek.

1950 Inspection notes (present order no. 98, photo no. 97) as in Bayliff, 1959, Appendix C, p. 104

100. Original monument in solid foundation; badly chipped on east side. Lettering indistinct, especially "M."

1979-81 Inspection notes: order no. 97 (100); photos/negatives/slides no. 97 (100) 97 (100). Original M&D milestone of 1767 in place, in fair condition, firmly set. Most of E/S chipped off; letters distinct, but all surfaces badly weathered and nicked; chips all edges and corners. BM set in apex. Protected by site.

SURROUNDING PROPERTY OWNERS (MD/PA): names, addresses, phones tax map 12, block , P. 5 , deed 499 / 289, acres 11.76 Claude T. Belew, Sr., Millers Church Road, Route 5, Hagerstown, MD 21740 Phone: 301/739-7738

, deed PA: tax map , block , P. , acres

RECORDED BY: names, addresses, phones, dates Alice Martin 10/13/80 Phone: 301/472-2128 14308 Mount Ave., Phoenix, MD 21131 Assisted by Clyde E. Martin

Also see: reverse side X , B&W photos X , negatives X , color slides X , maps X MHT-HSI form , other

LOCATION, continued

deciduous woods; about 2' W of end of short stretch of old stone farm wall. Cannot be seen from any rd or easily from nearby.

DIRECTIONS TO SITE, continued

to hike through their property to inspect stone. Hike/up through the old orchard on W/S of Belew house to fenceline & open field (about 500'); follow fence E & uphill (on field side) to point where/wire fence joins old loose stone wall. Monument is right there.

NOTES

Mrs. Belew (Clara) was very hospitable and helpful; gave us good directions as to how to find stone, and allowed us to park in her drive. The stone was badly damaged by setting of the triangulation station disk, is still cracking (apparently from this); and, as can be seen from the B&W photos more chips were ready to drop off the top. MGS will want to contact owners of property surrounding the stone, secure any loose chips and make sure the stone is not further damaged. Whoever inspects this next may want to approach site simply following E-W fenceline from Shoemaker Rd E (if field is still open and grassy). In this case: contact family at interesting old stone farmhouse W/S Shoemaker Rd (who can observe anything going on in that field!)

B&W PHOTOS/NEGATIVES

5x7 NW corner (1980.27.17A), Alice Martin 10/13/80

5x7 SE corner (1980.27.12A), "

3½x5 Closeup of top, showing USC&GS triangulation station disk (1980.27.16A), Alice Martin 12/13/80

3½x5 View NW: of stone & setting (1980.27.13A), Alice Martin 10/13/80


COLOR SLIDES

2x2 NW corner (1980.29.6), Alice Martin 10/13/80 2x2 SE corner (1980.29.4), " "

MAPS

USGS 7%' topographic quadrangle section 1900-03 Resurvey engineer's map (Plate XXXVII), updated MD tax map section

OTHER





MASER FIXER SETLINE: MILESTONE 9 (1)

OFF NE MILLERS CHURCH DV., LEITERSBURG, MD.

SECENER (M/-)

PHOTO: PLICE HARTIN (1980. 27. 124) 10/2 80



MASON EDIXON WEST LINE: MILESTONE 97(100)

OFF N/S MILERS CHURCH RD

LESTERS EURO, MO. VICINITY

SE CORDER SHOWING WEND OF

PRONE WALL REMAINS + STONE +

OPEN FIELDS TO NW

PHOTO: ALICE HARTIN (1980, 27. 13A)

10/13/80



MGS WA-I-48H

MASON & DIXON WEST LINE: MILESTONE 97 (100)

OFF N/S MILLERS CHURCH RD, LETTERSBURG, MT.

NW CORNER (P)-

PHETE; ALICE MARTIN (1980.27. 174 10/13/80



MGS WA- T-484

MASON EDIXON WEST LINE: MILESTONE 97 (100) OFF N/S MILERS CHURCH RD

LEITERSBURG, MD., UKINITY

CLOSEUP OF TOP & TRIANGULATION STATION DISK (BNDRY MON NO 97 1939) FROM NIS OF MILESTENE NOTE: MUCH OF EAST FACE IS GONE PHOTO: ALKE MARTIN (1980.27.16A)

10/13/80